

Message

From: Smallbeck, Donald R. [donald.smallbeck@woodplc.com]
Sent: 1/29/2019 4:57:57 PM
To: 'JERRARD, CATHERINE V CIV USAF HAF AFCEC/CIBW' [catherine.jerrard@us.af.mil]; 'Wayne Miller' [Miller.Wayne@azdeq.gov]; d'Almeida, Carolyn K. [dAlmeida.Carolyn@epa.gov]; Pearson, Stuart C. [stuart.pearson@woodplc.com]
CC: d p [DPope@css-dynamac.com]; Davis, Eva [Davis.Eva@epa.gov]; GANGNUSS, GREGORY G GS-14 USAF HAF AFCEC/CIBP [gregory.gangnuss@us.af.mil]; 'Geoff Watkin' [Geoff.Watkin@SpecProSvcs.com]; Nicole Goers [Nicole.Goers@TechLawInc.com]; 'Brasaemle, Karla' [KBrasaemle@TechLawInc.com]; 'Rohrbaugh, Amanda' [ARohrbaugh@TechLawInc.com]; 'Bo Stewart' [bo@praxis-enviro.com]; 'William Hughes' [William.Hughes@SpecProSvcs.com]; 'steve@uxopro.com' [steve@uxopro.com]; 'Jennings, Eleanor' [Eleanor.Jennings@parsons.com]; 'Panzino, Paula@azdeq.gov' [Panzino.Paula@azdeq.gov]
Subject: ST012 Site Activities

Activities Through Last Week (1/25)

- SVE Operation
- LNAPL checks
- Continued extraction and treatment- 57.8 gpm reading on 1/23, ~12.7 million total gallons treated since startup of EBR extraction.
- Extraction pump replacements/repairs implemented
- Operating Extraction Wells: CZ07, CZ18, CZ21, UWBZ21, UWBZ22, UWBZ26, UWBZ27, UWBZ30, LSZ09, LSZ11, LSZ12, LSZ23, LSZ37, LSZ38, LSZ39, UWBZ28/LSZ51
- Extraction Wells Currently Down: none
- Extraction Wells Removed from Pilot Plan (FVM 7): CZ19, LSZ28, LSZ29
- Extraction Wells to be Added to Pilot Plan in future (FVM7): UWBZ25, LSZ43
- Replaced variable frequency drive for catalytic oxidizer on 1/23/19. Successful restarted. Shut down on 1/25 due to high condensate from air stripper. Low ambient temperature generating high moisture from air stripper
- Injections into UWBZ33:
 - 4 tons sodium sulfate mixed into 10,000 gallons 1/9-1/10/19
 - 5 tons in 10,000 gallons 1/16-1/17/19
 - 4 tons in 10,000 gallons 1/24-1/25/19

This week (1/28-2/1)

- SVE Operation
- Continue extraction
- Inject sulfate at UWBZ36
- Oxidizer move scheduled for 2/1/19

Next Week (2/4-2/8)

- SVE Operation
- Continue extraction
- Receive additional sodium sulfate shipment
- Mix additional batch(es) for injections in UWBZ (depending on timing of receipt of shipment)
- Change over SVE from flame oxidizer to oxidizer from ST035

This message is the property of John Wood Group PLC and/or its subsidiaries and/or affiliates and is intended only for the named recipient(s). Its contents (including any attachments) may be confidential, legally privileged or otherwise protected from disclosure by law. Unauthorized use, copying, distribution or disclosure of any of it may be unlawful and is strictly prohibited. We assume no responsibility to persons other than the intended named recipient(s) and do not accept liability for any errors or omissions which are a result of email transmission. If you have received this message in error, please notify us immediately by reply email to the sender and confirm that the original message and any attachments and copies have been destroyed and deleted from your system.

If you do not wish to receive future unsolicited commercial electronic messages from us, please forward this email to: unsubscribe@woodplc.com and include "Unsubscribe" in the subject line. If applicable, you will continue to receive invoices, project communications and similar factual, non-commercial electronic communications.

Please click <http://www.woodplc.com/email-disclaimer> for notices and company information in relation to emails originating in the UK, Italy or France.

As a recipient of an email from a John Wood Group Plc company, your contact information will be on our systems and we may hold other personal data about you such as identification information, CVs, financial information and information contained in correspondence. For more information on our privacy practices and your data protection rights, please see our privacy notice at <https://www.woodplc.com/policies/privacy-notice>
